

CELANEX® 3300SW1

30% glass-fiber reinforced; tribological modified grade; for friction and wear applications Celanex 3300SW1 is a 30% glass filled PBT with excellent wear characteristics.

Product information

Part Marking Code (PBT+PTFE)-GF30 ISC	11469
---------------------------------------	-------

Rheological properties

Melt mass-flow rate	17 g/10min	ISO 1133
Melt mass-flow rate, Temperature	250 °C	
Melt mass-flow rate, Load	2.16 kg	
Moulding shrinkage range, parallel	0.3 - 0.5 %	ISO 294-4, 2577
Moulding shrinkage range, normal	0.7 - 0.9 %	ISO 294-4, 2577

Typical mechanical properties

Tensile Modulus	9600	MPa	ISO 527-1/-2
Stress at break, 5mm/min	125	MPa	ISO 527-1/-2
Strain at break, 5mm/min	2.8	%	ISO 527-1/-2
Flexural Modulus	8950	MPa	ISO 178
Flexural Strength	195	MPa	ISO 178
Charpy impact strength, 23°C	50	kJ/m ²	ISO 179/1eU
Charpy notched impact strength, 23°C	8	kJ/m ²	ISO 179/1eA
Hardness, Rockwell, M-scale	88		ISO 2039-2

Thermal properties

Melting temperature, 10°C/min	224 °C	ISO 11357-1/-3
Temp. of deflection under load, 1.8 MPa	212 °C	ISO 75-1/-2

Other properties

Density	1620 kg/m ³	ISO 1183
Deligity	1020 kg/III	130 1103

Injection

Drying Temperature	120 - 130	°C
Drying Time, Dehumidified Dryer	4	h
Processing Moisture Content	0.02	%
Max. mould temperature	65 - 93	°C
Injection speed	medium-fast	

Additional information

Injection molding

Rear Temperature 450-470(230-240) deg F (deg C)

Center Temperature 460-480(235-250) deg F (deg C)

Front Temperature 470-500(240-260) deg F (deg C)

Nozzle Temperature 480-500(250-260) deg F (deg C)

Melt Temperature 460-500(235-260) deg F (deg C)

Printed: 2023-09-14 Page: 1 of 2







CELANEX® 3300SW1

Mold Temperature 150-200(65-93) deg F (deg C) Back Pressure 0-50 psi Screw Speed Medium Injection Speed Fast

Injection speed, injection pressure and holding pressure have to be optimized to the individual article geometry. To avoid material degradation during processing low back pressure and minimum screw speed have to be used. Overheating of the material has to be avoided, in particular for flame retardant grades.

Processing Texts

Pre-drying To avoid hydrolytic degradation during processing, CELANEX resins have to be

dried to a moisture level equal to or less than 0.02%. Drying should be done in a dehumidifying hopper dryer capable of dewpoints <-40°F (-40°C) at 250°F

(121°C) for 4 hours.

Longer pre-drying times/storage For subsequent storage of the material in the dryer until processed (<= 60 h) it is

necessary to lower the temperature to 100° C.

Injection molding Rear Temperature 450-470(230-240) deg F (deg C)

Center Temperature 460-480(235-250) deg F (deg C) Front Temperature 470-500(240-260) deg F (deg C) Nozzle Temperature 480-500(250-260) deg F (deg C) Melt Temperature 460-500(235-260) deg F (deg C) Mold Temperature 150-200(65-93) deg F (deg C)

Back Pressure 0-50 psi Screw Speed Medium Injection Speed Fast

Injection speed, injection pressure and holding pressure have to be optimized to the individual article geometry. To avoid material degradation during processing low back pressure and minimum screw speed have to be used. Overheating of the material has to be avoided, in particular for flame retardant grades.

Printed: 2023-09-14 Page: 2 of 2



