

Technical information

TEREZ[®] GT2 300 H G30

Polyarylamid with 30% glass fiber reinforced and heat stabilization



TECHNICAL DATA SHEET

Product text

For all kind of injection molding parts

Properties	Value	Unit	Test method
Density	1,4200	g/cm ³	ISO 1183
Impact strength Charpy (Notched 23°C), dry	6	kJ/m ²	ISO 179
Impact strength Charpy (Notched 23°), conditioned	7	kJ/m ²	ISO 179
Impact strength Charpy 23°C, dry	45	kJ/m ²	ISO 179
Impact strength Charpy (23°), conditioned	50	kJ/m ²	ISO 179
Tensile-modulus, dry	12000	MPa	ISO 527
Tensile-modulus, conditioned	11500	MPa	ISO 527
Tensile stress at break, dry	195	MPa	ISO 527
Tensile stress at break, conditioned	180	MPa	ISO 527
Elongation at break, dry	1,90	%	ISO 527
Elongation at break, conditioned	2,30	%	ISO 527
HDT 1,80 MPa	225	°C	ISO 75
Melting point	237	°C	ISO 11357-3
Coeff. of linear therm. expansion (parallel)	0,18	E-4/°C	ISO 11359-1/-2
Coeff. of linear therm. expansion (normal)	0,4	E-4/°C	ISO 11359-1/-2
CTI	370	V	IEC 60112
Electric strength	30,00	kV/mm	IEC 60243-1
Burning Behav. at thickness h	HB	class	UL 94
Thickness tested	1,6	mm	UL 94
UL recognition	-		UL 94
Water absorption	2,00	%	ISO 62
Moisture absorption	0,21	%	ISO 62

TER Plastics
POLYMER GROUP



PROCESSING DATA SHEET

Processing guidelines for injection molding of TEREZ GT2 300 H G30

The processing data sheet provides guidelines about processing as well as pre-drying.

MATERIAL PREPARATION

Storage

Store in a dry place protected from direct sunlight. Avoid all sources of ignition like extreme heat, sparks, or open flame.

Drying

For the manufacturing of mechanically and optically optimal injection molding parts, we recommend following pre-drying conditions according to the table below. If the container is open (wet granules), the drying time can be extended accordingly.

Dry air dryer

Temperature	110°C
Time	6 - 8 hours
Due point	-40°C

Residual moisture

<= 0.05% (recommended)
max. 0.1% (standard)

MACHINE REQUIREMENTS

PROCESSING

Basic settings

The following basic settings are generally to be selected:

Temperatures

Processing temperatures

Hopper 60 - 80 °C
Center 250 - 280 °C
Nozzle 260 - 290 °C

Mold temperature

Temp. 120 - 140°C

Residence time

You should try to keep the residence time short, especially at high temperatures to avoid material degradation.

Residence times in the cylinder

max. 265 °C / 8 min.

Instructions for cleaning

The aggregate can be cleaned by using low MFI polypropylene. You can also use standard cleaning granulate.